

System	Date of Issue	Bulletin Number	Bulletin Type
G2V2	9/26/14	00019	<input checked="" type="checkbox"/> Field Service Action <input type="checkbox"/> Technical Service Bulletin <input type="checkbox"/> Technical Service Advisory

Title: HCU Software Update

Issue:

Software update addresses nuisance issues and adds display improvements related to fault handling.

Applies To:

1FVACYDT0FHGD3349	1HTMMAAN0EH073774	1HTMMAAN6EH068241	4UZAARDT7ECFX4125
1FVACYDT0FHGD3352	1HTMMAAN2EH068236	1HTMMAAN8EH068239	4UZAARDT7ECFY2354
1FVACYDT2FHGF2906	1HTMMAAN2EH073775	1HTMMAAN8EH068242	4UZAARDT8ECFY0550
1FVACYDT4FHGF2907	1HTMMAAN4EH068237	1HTMMAAN9EH068234	4UZAARDT9ECFY2355
1FVACYDT7FHGD3350	1HTMMAAN4EH068240	1HTMMAAN9EH073773	4UZAARDU3FCGF1160
1FVACYDT8FHGJ5833	1HTMMAAN5EH073771	1HTMMAANXFH122187	4UZAARDU6FCGJ6388
1FVACYDT9FHGD3351	1HTMMAAN6EH029178	4UZAARDT1ECFY5086	4UZAARDU6FCGJ6391
1HTMMAAN0EH068235	1HTMMAAN6EH068238	4UZAARDT4FCGB5324	4UZAARDU8FCGJ6389

1FVACXCY3FHGE4465	1HTJTSKR9EH052340	3FRXF7FG5FV671211	3FRYX7FL2DV026107
1FVACXDT0EHFU8251	1HTMKAZN7FH567738	3FRXF7FK6CV431150	3FRYX7FL2DV026110
1FVACXDT4EHFZ4035	1HTMKAZRXEH783343	3FRYF7FE1CV353245	3FRYX7FL4DV026108
1FVACXDT8EHFU8241	1HTMMAAN7EH073772	3FRYF7FE3CV353246	3FRYX7FL5DV026103
1FVACYCY0EHFX1130	1HTMMAANXFH526106	3FRYF7FE8CV353243	3FRYX7FL6DV026109
1FVACYCY8FHGE8002	1HTMMAAR1AH271521	3FRYF7FEXCV353244	3FRYX7FL7DV026104
1FVACYDT0FHGA6457	1HTMMAAR3FH526161	3FRYF7FL1DV061076	3FRYX7FL9DV026105
1FVACYDT4BDAY7502	1HTMMAAR4AH176726	3FRYF7FL4DV061072	3HAMKAAR3FL127542

The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. Warranty Policy documentation determines Warranty coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Odyne Systems, LLC reserves the right to supersede this information with updates. The most recent information is available through Odyne on-line technical resources.

1FVACYDT6BDAY7503	1HTMMAARX9H133102	3FRYF7FL6DV061073	3HAMKAAR5FL111908
1FVACYDT7EHFV5672	1HTWGAAR5EH105251	3FRYF7FL8DV026101	3HAMKAARXFL127540
1FVACYDT7FHGA6455	1HTWGAAR7EH095922	3FRYF7FLXDV026102	3HAMKAZN5EL013882
1FVACYDT7FHGE2548	1HTWGAAR7EH105252	3FRYF7FLXDV061075	3HAWKAZN7FL644465
1FVACYDT9FHGA6456	1HTWGAAR9EH095923	3FRYX7FE0CV353234	3HAWKAZN9FL644466
1FVACYDT9FHGE2549	1HTWGAAR9EH105253	3FRYX7FE2CV353235	3HAWNAZT6FL560823
1FVH65CY9FHGE5871	1HTWGAZT0FH518065	3FRYX7FE6CV353237	3HAWNAZT8FL560824
1FVHCYC1FHGG7828	2NKHHJ8X1EM418899	3FRYX7FE6CV353240	4UZAARDU4FCGJ6387
1FVHCYCYXFHGG7827	2NKHHJ8X4EM418900	3FRYX7FE8CV353238	4UZAARDU4FCGJ6390
1FVHG3DV4FHGE0053	3ALACXDT6EDFX9591	3FRYX7FE8CV353241	4UZAARDU8FCGJ6392
1FVHG3DV6FHGE0054	3ALACYDT6EDFV2462	3FRYX7FEXCV353239	
1FVHG3DV8FHGE0055	3ALACYDT8EDFV2463	3FRYX7FEXCV353242	
1FVHG5CY0FHGE5872	3ALACYDTXEDFV2464	3FRYX7FL0DV026106	

Special Tools or Software Required:

Where Available	Type of Tool	Equipment Description

Action: Update HCU software with the minimum software version B274.

Service Procedure:

Before Starting Programming Procedure:

1. Refer to HCU Service Procedure documentation.

Parts Required:

Part Number	Description	Qty
NA	NA	NA

The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. Warranty Policy documentation determines Warranty coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Odyne Systems, LLC reserves the right to supersede this information with updates. The most recent information is available through Odyne on-line technical resources.

Warranty Information:

Code	Description	Time
00019	HCU Software Update	.8

The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. Warranty Policy documentation determines Warranty coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Odyne Systems, LLC reserves the right to supersede this information with updates. The most recent information is available through Odyne on-line technical resources.