

System	Date of Issue	Bulletin Number	Bulletin Type
G2V2	4/8/2015	00022	<input checked="" type="checkbox"/> Field Service Action <input type="checkbox"/> Technical Service Bulletin <input type="checkbox"/> Technical Service Advisory

Title: CARB EPTO Conversion

Issue: CARB States Require EPTO only

Applies To:

3FRYF7FL8DV026101	3FRYX7FL0DV026106	3HAWNAZT6FL560823	3FRXF7FG5FV671211
3FRYF7FLXDV026102	3FRYX7FL2DV026107	3HAWNAZT8FL560824	1HTMMMMN8FH686398
3FRYX7FL5DV026103	3FRYX7FL4DV026108	1FVHG3DV4FHGE0053	3HAMMAAN7FL744336
3FRYX7FL7DV026104	3FRYX7FL6DV026109	1FVHG3DV6FHGE0054	1FVACXDT3FHGT1383
3FRYX7FL9DV026105	3FRYX7FL2DV026110	1FVHG3DV8FHGE0055	TBD - Odyne # 2129

Special Tools or Software Required:

Where Available	Type of Tool	Equipment Description

Action: Update calibrations in HCU for EPTO

Service Procedure:

1. Follow HCU Service Procedure
2. Update HCU calibrations to latest calibrations listed on the calibration spreadsheet

The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. Warranty Policy documentation determines Warranty coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Odyne Systems, LLC reserves the right to supersede this information with updates. The most recent information is available through Odyne on-line technical resources.

Parts Required:

Part Number	Description	Qty

Warranty Information:

Code	Description	Time
00022	CARB EPTO Conversion	NA

The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. Warranty Policy documentation determines Warranty coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Odyne Systems, LLC reserves the right to supersede this information with updates. The most recent information is available through Odyne on-line technical resources.